

Open job on data collector
 <File> ---- <export coordinates>
 Click on drop down arrow ---- <select all points>
 Select the type of file to export ---- <coordinate (.CR5)>
 Click <Export>
 Click <Next>
 Select <Sequential>
 Click <Export>
 Name the file
 Exit Survey Pro

Plug data collector into the USB port connected to the computer

Click <NO> when it ask to set up partnership
 Click <Next>
 This will connect the computer to the data collector

Click on <File> ---- <Explore>



Open ---- <**TDS files**>

Right click on file you exported into a .CR5 file

Select <**Copy**> from the menu

Browse in Window's Explorer to where your job data is stored and then paste the file into the job directory

Recommended: H:\Projects\landowner\

Close connection